

**Government of Andhra Pradesh**  
**A.P. State Disaster Response and Fire Services Department**

**Periodical Renewal Fire Certificate**

From:  
Regional Fire Officer  
Zone-2,Rajahmundry  
Andhra Pradesh.

To:  
REGIONAL FIRE OFFICER,

**File No: 28034/KRI/RFO/2025, Date:20/09/2025**  
**Occupancy NoC RC Number: 408/RFO/ER/2019**

Sir,

Sub: Andhra Pradesh State Disaster Response and Fire Services Department - Periodical Fire Certificate to the existing Non Multi Storeyed Building of **M/S VIDYARANYA EDUCATIONAL SOCIETY, represented by PARUCHURI SRINIVASARAO, VIDYARANYA EDUCATIONAL SOCIETY, D.NO-7-374/7 & 378/8, THOTLAVALURU, VUYYURU, KRISHNA DISTRICT, PIN-521165** - Regarding.

- Ref:
1. G.O.Ms.NO.218 Home (Prisons & Fire) Department, Dated.22-12-2023
  2. This Office Delegation of Powers Rc.No.3350/Audit/NOC/2012, Dated.02-05-2023.
  3. This Office NOC for Occupancy Rc No. 408/RFO/ER/2019, Dt.21/06/2019
  4. Renewal NOC For Occupancy 408/RFO/ER/2019, Dt.21/06/2020
  5. Online Application for Renewal NOC of PARUCHURI SRINIVASARAO, VIDYARANYA EDUCATIONAL SOCIETY, D.NO-7-374/7 & 378/8, THOTLAVALURU, VUYYURU, KRISHNA DISTRICT, PIN-521165 - Inspection report called for Regarding.
  6. Online Inspection Report submitted by Officers of this Department on 19-09-2025.

-- x --

The Management of M/S VIDYARANYA EDUCATIONAL SOCIETY, represented by PARUCHURI SRINIVASARAO, VIDYARANYA EDUCATIONAL SOCIETY, D.NO-7-374/7 & 378/8, THOTLAVALURU, VUYYURU, KRISHNA DISTRICT, PIN-521165 has requested to issue Periodical Fire Certificate duly remitting the Fire Precautionary fee for Rs.110300/- vide challan No. 91180366152025, Dated 16/09/2025 at ONLINE PAYMENT, ONLINE PAYMENT.

**BBLOCK-1 ,BLOCK-IV ,BLOCK-V ,BLOCK-III ,BLOCK-VI  
BLOCK-II ,BLOCK-VIII ,BLOCK-VII**

1. This certificate is being issued as per G.O.Ms.No:218,Home(Prisons & Fire),Dt:22-12-2023
2. The No Objection Certificate for Occupancy was issued vide reference cited (3) and the Management has also obtained Periodical Renewal Fire Certificate for vide reference 4th cited to the existing Non Multi Storeyed Building.
3. The Officers of the department have recommended to issue The Periodical Renewal Fire Certificate **PARUCHURI SRINIVASARAO VIDYARANYA EDUCATIONAL SOCIETY, D.NO-7-374/7 & 378/8, THOTLAVALURU, VUYYURU, KRISHNA DISTRICT, PIN-521165**, subject to the following conditions.

SI As Builder	As Occupant	As Security Personnel
---------------	-------------	-----------------------

1	All the fire protection arrangements shall be maintained in good condition as seen during inspection.	All the escape/exit routes shall not be kept locked/blocked or encroached	All the occupants must know the correct method of operation of the fire fighting system installed.
2	Any loss of life or property due to non-functioning of fire safety measures and other installations shall be the responsibilities of the management.	All occupants shall be trained to operate the fire safety equipments during emergency.	Mock drills should be conducted once in 3 months for initial two years. Thereafter, once in every 6 months.
3	Addition / alteration; if any in the building may be verified by building authority.	Mock drills should be conducted once in 3 months for initial two years. Thereafter, once in every 6 months.	All security personnel shall be trained to operate the fire safety equipments during emergency.
4	This is Only for Fire Safety Point of View.	Raise the alarm if the fire cannot be controlled; Evacuate the area completely at once with nearest safe exit.	Attack the fire using available fire equipment only if you feel capable of controlling. If not, take all steps to isolate the area by closing doors and windows.

The applicant/management must train 40% of their total work force on 3 days Basic Firefighting Course under AP Fire Services and Civil Defence Training Institute, Sattenapalli or Regional Training Centres of the Department.

4. This Periodical Renewal Fire Certificate is valid from 19/09/2025 to 18/09/2028.

5. The Responsibility/liability of the owner/occupier or both to maintain Fire safety measures in good condition in all times, in accordance with AP Fire safety Act 1999 and Rules, 2006.

6. Challan Info:

Challan Number	Challan Date	Challan Amount
91180366152025	16/09/2025	110300

The following deficiencies/suggestions are identified by the officers of the department and needs to be attended to by the management.

*[Handwritten signature]*  
20/9/25

**Paruchuri**  
**Srinivasarao**

Digitally signed

by Paruchuri

Srinivasarao

Date:

2025.09.24

18:25:24 +05'30'


*[Handwritten signature]*  
**Manager**  
**Sri Srinivasa Aksharalayam EM School**  
**CBSE Affiliated 130720**

*[Handwritten signature]*  
**Principal**  
**Sri Srinivasa Aksharalayam EM School**  
**CBSE Affiliated 130720**

The Inspection Committee consists of DDRFO-Krishna District and FSI0-Vuyuur has inspected the premises and offered the remarks as Recommended : Namaskaram Sir, 1).Building Height Discrepancy - Block-1 : The management has declared the height of Block-1 as 12.00 meters. However, during the inspection, the actual height was found 14.40 meters, comprising Ground + 3 upper floors, with Educational Occupancy. 2).Internal Staircases : Total of 03 internal staircases have been provided in the building. 3).Fire NOC Status :The management has previously obtained one Renewal NOC Vide Rc.No.14873/KRI/RF0/2020 Dt.24.11.2020 and has currently applied for the second Renewal NOC. 4). Fire Safety Equipment: All provided fire safety equipment is found sufficient and in good working condition at the time of inspection. 5). Additional Fire-Fighting Installations : The premises are equipped with an increased number of Hose Reels, Downcomers, and Landing Valves, Manual Call points beyond the minimum requirement. 6).Demolition of Blocks :Blocks 4, 5, and 6 have been found demolished during the inspection. 7). The total built-up area of all blocks (post demolition of Blocks 4, 5, and 6) is 8116.14 square meters. 8).The management has remitted an amount of Rs.1,10,300/- under STO Code: 05181005001 (STO Vuyyuru). However, the correct DDO Code is 72011005001 (Krishna District, Machilipatnam). 9).It was observed that the actual built-up area of Block -1, 3rd Floor, is 1761.37 Sq. Meters, whereas the area shown by the management was 913.61 Sq. Meters. The discrepancy in floor area was duly acknowledged by the management. To regularize the excess floor area, the management has remitted an amount of Rs. 11,500/- towards the Excess Floor Area Challan for the purpose of obtaining the Annual Fire Safety Certificate for Occupancy (valid for 03 years). In view of the compliance with the fire safety norms and the remittance of applicable charges, it is hereby recommended to issue the Annual Fire Safety Certificate for Occupancy. The Management has been advised to impart training to 40% of the Occupants and employees working at the Building in 3 days Basic course training in Fire prevention and firefighting at A.P. State/Regional Training Institute or at local Fire Station level within 3 months and compliance the particulars of trained Occupants and employees. It shall be the responsibility of the Management to ensure that the installed fire-fighting equipment is maintained in working condition 24/7. In case of failure, the Management/Occupier/Owner will be held liable under the relevant laws in force.

Paruchuri Digitally signed  
by Paruchuri  
Srinivasarao  
Date: 2025.09.24  
18:24:44 +05'30'

Your Sincerely,

  
Regional Fire Officer  
Zone-2, Rajahmundry  
Andhra Pradesh.

Copy to PARUCHURI SRINIVASARAO, M/S VIDYARANYA EDUCATIONAL SOCIETY, D.NO-7-374/7 & 378/8, THOTLAVALLURU, VUYYYURU, KRISHNA DT

Copy to Chief Office for Record Purpose

20/09/2025, 17:40

A.P. State Disaster Response and Fire Services Department

Copy to District Fire Officer Concerned  
Copy to Assistant District Fire Officer Concerned  
Copy to Station Fire Officer Concerned

Paruchuri  
Srinivasarao  
Digitally signed  
by Paruchuri  
Srinivasarao  
Date:  
2025.09.24  
18:26:07 +05'30'

  
Manager  
Sri Srinivasa Aksharalayam EM School  
CBSE Affiliated 130720

  
Principal  
Sri Srinivasa Aksharalayam EM School  
CBSE Affiliated 130720